

SPARE TIMES



NEW DEDICATED SECURE INVENTORY STOCK AREA IN MIDDLETOWN, OH

Aftermarket inventory now in the U.S.

With the growing need of a larger customer base in North America, Ventilex USA Inc. and Ventilex B.V. in the Netherlands is happy to announce that we have made advancements in service by expanding aftermarket inventory parts to be stocked locally at the Ventilex USA Inc. Middletown, OH

location. This effort will increase efficiency of getting routine and critical spare parts to our customers faster and cheaper, so that downtime for maintenance can be reduced.

As greater availability of stocked aftermarket parts increases this also presents the ability to offer parts at

reduced costs. Also avoiding importing each individual order separately, shipping and customs costs are significantly reduced as well.

These efforts continue our goals of making the entire aftermarket experience with Ventilex a true asset for our customers.

APRIL SHOWERS BROUGHT MAY SAVINGS!!

10% OFF

All orders in May 2012 over \$2000 for stock items. If it's on our shelf, you get the discount!

percentage deducted from price of aftermarket parts ordered from May 1-31, 2012


There's always time to get your parts on order if you plan ahead! With Ventilex USA's expanding inventory, you can save even more by ordering more than one of each part to keep on the shelf in case you need it. When you find yourself needing a replacement, you are still up and running while we get your new part to you to put back on your shelf!



SPARE SPOTLIGHT FOR THE MONTH

In the world of Ventilex Fluid Bed Dryer drives, one of the most critical components are the eccentric shaft bearing assemblies. The importance of making sure the clearances, lubrication, fittings, and secure nuts and bolts are correct, directly affects the efficient operation of the dryer/ cooler. If the bearings are misaligned, or are not maintained or installed properly, the results could be a broken bearing assembly. The result of course is your equipment being down until

Type 522-619 Split pillow block bearing assembly



the bearing(s) can be replaced. It is also important to maintain proper pressure levels in the air springs on your equipment. Too low or too high pressure will directly affect the loads that bearing assemblies must endure during normal operation. If you have questions about this information or would like to order replacement bearing assemblies, please don't hesitate to contact Ventilex USA Inc.'s aftermarket department right away.



TECHNICAL SERVICE



FASTER CHEAPER SHIPPING



EXPANDING INVENTORY